



Concrete pour in balcony seating. Protections have been installed over the new stage slab in preparation for overhead structural demolition (beginning on 12/02).




Preparation for Small Venue CMU wall installation. Weather wall installation at Ground Level has begun.



View of Small and Medium Venues from the courtyard.




Storm piping delivered to site. Installation is upcoming during week of 12/02.




CMU installation at Medium Venue perimeter walls.

_ - - -



Preparation for HVAC unit installation.



18th Floor progress.