


Overhead structural demolition began this week, protections are installed on the new stage slab.




View of Small Venue weather wall from interior looking out at PPW courtyard.



Ductwork installation has started on Floor 2



View of Medium Venue from Floor.



Medium Venue CMU wall installation.



Medium Venue gallery CMU walls complete.



CMU block wall installation ongoing throughout.