

1 Pace Plaza East Renovation Progress Photos




Preparation for Small Venue CMU wall installation view of Small and Medium Venues from the Courtyard.

1 Pace Plaza East Renovation Progress Photos



CMU wall work ongoing at venue openings.




Slab openings for utilities and ductwork.

1 Pace Plaza East Renovation Progress Photos



DYfja YYYf]bg `Ufcb`]bghU`Ufcb`]g'cb[c]b[]b'A Uf]Ug`
Tower.



4th Floor paver removal for roof work.